

Control # 037420170317  
 Date Taken 03/16/2017  
 Service Meter Reading 0  
 Fluid Run Time 0  
 Fluid Added Gal / Qts 0 / 0  
 Fluid Status Sampled  
 Filter Changed No



**Lab One Inc.**  
 Oil Analysis since 1985

Mail to: PO Box 20210 - Phoenix, AZ 85036-0210  
 Ship to: 101 W Mohave St. - Phoenix AZ 85003

Phone  
 Local: 480-839-5221  
 Toll Free: 866-652-2663  
 Fax: 480-839-9987

**Normal**

Anti-Freeze	Negative
Water	Negative
Visc 100C	7.1
Iron (FE)	32
Chromium (CR)	0
Lead (PB)	4
Copper (CU)	8
Tin (SN)	2
Aluminum (AL)	9
Nickel (NI)	0
Silver (AG)	0
Silicon (SI)	5
Potassium (K)	1
Sodium (NA)	6
Boron (B)	99
Magnesium (MG)	3
Calcium (CA)	96
Barium (BA)	4
Phosphorus (P)	248
Zinc (ZN)	39
Molybdenum (MO)	1
Titanium (TI)	0
Vanadium (V)	0

1 of 1  
 03/17/2017  
 Make / Model  
 MCI 102N-3 B500  
 Unit/Serial  
 50654/DERRICK T  
 Compartment  
 Transmission  
 Fluid Type  
 ATF  
 WO / Reference

**Current Interpretation**

No abnormal wear or contaminants detected.

0000002071

W W Williams Truck LV  
 Attn: Corey  
 2680 Losee Road  
 North Las Vegas, NV 89030

Registered By  
 CANDY PHILLIPS  
 Interpreted By  
 PAUL KITTRICK

*This analysis is intended as an aid in predicting mechanical wear. No guarantee, expressed or implied, is made against failure of this component.*